

Article number: 98 001 00 00

SWS system programming for up to 30 tapping points

Initial instruction included. System programming is carried out strictly according to on-site conditions. Installation and system functionality must be present and correct (water, cabling and power supply); if not, additional costs will be incurred.



Necessary associated articles

Travel and departure costs per km from Olpe plant Article no: 98 105 00 00

Hint

- Available on request.